

COLLECTION

# AWELYE ATNWENGERRP BY CHARMAINE PWERLE

THE **RUG**  
COLLECTION  
AUSTRALIA

**tallira**  
FURNITURE



# AWELYE ATNWENGERRP

by Charmaine Pwerle



AKARLEY



ANJURRA



KWERRALYA



MALANGKA

**CONSTRUCTION** Handwoven

**COMPOSITION** 100% Tencel™

**STOCK SIZES (cm)** 200 x 290 / 250 x 350 / 300 x 400

**CUSTOM OPTIONS**

Custom sizes and commercial quality options available

**PILE TYPE** Cut Pile

**PILE HEIGHT** Approx. 5 mm

**THICKNESS** Approx. 10 mm

**FINISH** No Carving

**EDGE FINISH** Overlocked

**USE PURPOSE** Indoor

**SUITABILITY** Residential

Commercial (100% wool) option available through custom program

**CARE**

Professional clean only. Do not steam clean. Regular gentle vacuuming will remove any dust and debris. Do not wet your rug or apply detergent. Do not rub or scrub the rug, as it may cause permanent pile damage/disruption. Act on a spill as soon as it occurs by gently pressing with a clean, white cloth (or paper towel) to absorb as much liquid as possible, to reduce permanent damage.

**IMPORTANT** Use a flat head when vacuuming. To prevent excess fluffing, do not use a brush head or turn brush setting off.

**MANUFACTURING VARIATIONS**

All rugs are made by hand which means there is a slight chance that variations in size and colour can occur. Up to 5% variation in size and colour is considered acceptable. Variations in pile height and total thickness of 1-2 mm are considered acceptable.

**PRODUCT CHARACTERISTICS**

**SHEDDING** Often new rugs begin to produce fluff as a result of loose fibres that remain in the rug after the manufacturing process. Vacuum regularly and this will reduce over time.

**SPROUTING** Occasionally loose yarn ends will rise above the pile surface. This is a characteristic of this particular weave. Strands can be safely trimmed to the surface when this occurs with a pair of sharp scissors.

**SHADING** All cut pile rugs are susceptible to exhibit characteristics of shading over time. This is the result of the reversal of pile direction during use causing areas of the rug to appear to have changed colour. This effect is not a manufacturing fault nor can it be prevented.

## GET IN TOUCH

---

### SHOWROOM LOCATIONS

MELBOURNE  
(03) 9421 5133

SYDNEY  
(02) 8338 0107



VISIT US

---

### HEAD OFFICE

(03) 8555 3584

4/80 Fairbank Road  
Clayton South VIC  
Australia 3169

---

### EMAIL

[sales@therugcollection.com.au](mailto:sales@therugcollection.com.au)

---

### ONLINE

[therugcollection.com.au](http://therugcollection.com.au)  
[tallira.com.au](http://tallira.com.au)

