# REGENCY VN141

HANDLOOM KNOTTED WOOL & BAMBOO









### REGENCY VN141 RUG

in Dark Grey



Dark Grey

**Stock Sizes (cm)** 200 X 290 / 250 X 350 / 300 X 400

VIEW PRICING

Log in or Request a Trade Account

Construction Handloom knotted
Composition Wool & Bamboo
Custom Options No
Pile Type Cut pile
Thickness Approx 6 mm
Finish No Carving
Edge Finish Overlocked
Use Purpose Indoor
Suitability Residential





## REGENCY VN141 RUG

in Ivory



Ivory

**Stock Sizes (cm)** 200 X 290 / 250 X 350 / 300 X 400

VIEW PRICING

Log in or Request a Trade Account

Construction Handloom knotted
Composition Wool & Bamboo
Custom Options No
Pile Type Cut pile
Thickness Approx 6 mm
Finish No Carving
Edge Finish Overlocked
Use Purpose Indoor
Suitability Residential







Ivory

### **RUG CARE**

#### **IMPORTANT**

Use a flat head when vacumming. To prevent excess fuzzing, do not use a brush head or turn brush setting off. Vacuum regularly. Clean spills immediately. Never rub a spill, instead blot any liquids with a dry absorbent white cloth or paper towel. Some stains may be cleaned with a mild clear detergent and lukewarm water. If the stain cannot be removed, seek specialist advice. Do not machine wash.

#### MANUFACTURING VARIATIONS

All rugs are made by hand which means there is a slight chance that variations in size and colour can occur. Up to 5% variation in size and colour is considered acceptable. Variations in pile height and total thickness of 1-2 mm are considered acceptable.

#### **PRODUCT CHARACTERISTICS**

#### SHEDDING

Often new rugs begin to produce fluff as a result of loose fibres that remain in the rug after the manufacturing process. Vacuum regularly and this will reduce over time.

#### **SPROUTING**

Occasionally loose yarn ends will rise above the pile surface. This is a characteristic of this particular weave. Strands can be safely trimmed to the surface when this occurs with a pair of sharp scissors.

#### SHADING

All cut pile rugs are susceptible to exhibit characteristics of shading over time. This is the result of the reversal of pile direction during use causing areas of the rug to appear to have changed colour. This effect is not a manufacturing fault nor can it be prevented.





### GET IN TOUCH

#### SHOWROOM LOCATIONS

MELBOURNE SYDNEY

935 High Street 62-66 Mentmore Ave Armadale VIC Rosebery NSW Australia 3143 Australia 2018

#### HEAD OFFICE

(03) 8555 3584

4/80 Fairbank Road Clayton South VIC Australia 3169

#### **EMAIL**

sales@therugcollection.com.au

