

COLLECTION

PAVONA RUG
HANDWOVEN
WOOL/NYLON

THE **RUG**
COLLECTION
AUSTRALIA

tallira
FURNITURE



VIEW ONLINE



PAVONA RUG

COLOUR: LINEN

Stock Sizes (cm)
200 X 290 / 250 X 350 / 300 X 400

Construction Handwoven
Composition Wool/Nylon
Custom Options Not Available
Thickness Approx 15 mm
Edge Finish Overlocked
Use Purpose Indoor
Suitability Residential



LINEN

[VIEW PRICING](#)

[Log in](#) or [Request a Trade Account](#)



PAVONA RUG

COLOUR: TAUPE

Stock Sizes (cm)
200 X 290 / 250 X 350 / 300 X 400

Construction Handwoven
Composition Wool/Nylon
Custom Options Not Available
Thickness Approx 15 mm
Edge Finish Overlocked
Use Purpose Indoor
Suitability Residential



TAUPE

[VIEW PRICING](#)

[Log in](#) or [Request a Trade Account](#)

PAVONA RUG

HANDWOVEN WOOL/NYLON

tallira
by THE RUG COLLECTION



Linen



Taupe

RUG CARE

IMPORTANT

Use a flat head when vacuuming. To prevent excess fuzzing, do not use a brush head or turn brush setting off. Vacuum regularly. Clean spills immediately. Never rub a spill, instead blot any liquids with a dry absorbent white cloth or paper towel. Some stains may be cleaned with a mild clear detergent and lukewarm water. If the stain cannot be removed, seek specialist advice. Do not machine wash.

MANUFACTURING VARIATIONS

All rugs are made by hand which means there is a slight chance that variations in size and colour can occur. Up to 5% variation in size and colour is considered acceptable. Variations in pile height and total thickness of 1-2 mm are considered acceptable.

PRODUCT CHARACTERISTICS

SHEDDING

Often new rugs begin to produce fluff as a result of loose fibres that remain in the rug after the manufacturing process. Vacuum regularly and this will reduce over time.

SPROUTING

Occasionally loose yarn ends will rise above the pile surface. This is a characteristic of this particular weave. Strands can be safely trimmed to the surface when this occurs with a pair of sharp scissors.

SHADING

All cut pile rugs are susceptible to exhibit characteristics of shading over time. This is the result of the reversal of pile direction during use causing areas of the rug to appear to have changed colour. This effect is not a manufacturing fault nor can it be prevented.

GET IN TOUCH

SHOWROOM LOCATIONS

MELBOURNE
(03) 9421 5133

SYDNEY
(02) 8338 0107



VISIT US

HEAD OFFICE

(03) 8555 3584

4/80 Fairbank Road
Clayton South VIC
Australia 3169

EMAIL

sales@therugcollection.com.au

ONLINE

therugcollection.com.au
tallira.com.au

